

FREY FARM LANDFILL METHANE MONITORING PROGRAM  
SAMPLE POINT INSPECTION FORM

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 3/7/24	DATE 6/20/24	DATE 9/26/24	DATE 12/20/24
1	PUMP STATION; AIR SPACE	0	0	0	0
2	PUMP STATION; STRUCTURE INTERIOR	0	0	0	0
3	MANHOLE 1S	0	0	0	0
4,5,6,7	(DELETED)	No Longer Monitored			
8	SEE MAP	0	0	0	0
9	SEE MAP	0	0	0	0
10	SEE MAP	0	0	0	0
11	SEE MAP	0	0	0	0
12	SEE MAP	0	0	0	0
13	SEE MAP	0	0	0	0
14	SEE MAP	0	0	0	0
15	SEE MAP	0	0	0	0
16	SEE MAP	0	0	0	0
17	SEE MAP	0	0	0	0
18	FFLTP; INFLUENT PIPE GALLEY	0	0	0	0
19	MANHOLE 2PB	4	0	0	0
20	MANHOLE 2IA-P	0	0	0	0
21	MANHOLE 2IB-P	0	0	0	0
22	NW CELL 2 (SEE MAP)	0	0	0	0
23	SEE MAP	0	0	0	0
24	SEE MAP	0	0	0	0
25	MANHOLE 3A-S	0	0	0	0
26	MANHOLE 3A-P	0	0	0	0
27	FFMP005W	0	0	0	0
28	FFMP013W <sup>1</sup>	NA	NA	NA	NA
29	FFMP016W <sup>2</sup>	NA	NA	NA	NA
30	TRUCKWASH DRAIN PIT	0	0	0	0
31	MAINTENANCE BUILDING OFFICE	0	0	0	0
32	MAINTENANCE BUILDING LUNCH ROOM	0	0	0	0
33	MAINTENANCE BUILDING STORAGE AREA	0	0	0	0
34	COMPLIANCE BUILDING LAB	0	0	0	0
35	COMPLIANCE BUILDING OFFICE	0	0	0	0
36	FFLTP EQ. TANKS METER PIT	0	0	0	0
37	CELL 1 CLEANOUT	No Longer Monitored			
38	LASA PUMP STATION STRUCTURE INTERIOR	0	0	0	0
39	LASA PUMP STATION AIR SPACE	0	0	0	0
40	MANHOLE 4S	0	0	0	0

<sup>1</sup> FFMP013W Location - Well Abandoned

<sup>2</sup> FFMP016W Location - Well Abandoned June 2021

FREY FARM LANDFILL METHANE MONITORING PROGRAM  
SAMPLE POINT INSPECTION FORM

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 3/7/24	DATE 6/20/24	DATE 9/26/24	DATE 12.20.24
41	MANHOLE 4P	0	0	0	0
42	MANHOLE 5S	0	0	0	0
43	MANHOLE 5P	0	0	0	0
44	MANHOLE 5SW <sup>1</sup>	NA	NA	NA	NA
45	MANHOLE 5PB <sup>2</sup>	NA	NA	NA	NA
46	MANHOLE 6S	0	0	0	0
47	MANHOLE 6P	0	0	0	0
48	MANHOLE 6-FM	0	0	0	0
49	FFGMP001 <sup>3</sup>	NA	NA	NA	NA
50	FFGMP002	0	0	0	0
51	FFGMP003	0	0	0	0
52	FFGMP004	0	0	0	0
53	FFGMP005	0	0	0	0
54	FFGMP006	0	0	0	0
55	FFGMP007	0	0	0	0
56	FFGMP008 <sup>4</sup>	NA	NA	NA	NA
57	FFGMP01R	0	0	0	0
58	FFGMP02R	0	0	0	0
61	FFGMP08R	0	0	0	0
	Atmospheric Pressure	29.99"	30.33"	30.05"	30.00"
	Air Temperature (Deg. C)	15.0°C	32.2°C	23.3°C	0.0°C

<sup>1</sup> MANHOLE 5SW Location - removed due to FFVE

<sup>2</sup> MANHOLE 5PB Location - removed due to FFVE

<sup>3</sup> FFGMP001 Location - removed March 2018

<sup>4</sup> FFGM008 Location - removed April 2018