FREY FARM LANDFILL METHANE MONITORING PROGRAM
SAMPLE POINT INSPECTION FORM

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 2/16/26	DATE	DATE	DATE
1	PUMP STATION; AIR SPACE	0			
2	PUMP STATION; STRUCTURE INTERIOR	0			
3	MANHOLE 1S	0			
4,5,6,7	(DELETED)	No Longer Monitored			
8	SEE MAP	0			
9	SEE MAP	0			
10	SEE MAP	0			
11	SEE MAP	0			
12	SEE MAP	0			
13	SEE MAP	0			
14	SEE MAP	0			
15	SEE MAP	0			
16	SEE MAP	0			
17	SEE MAP	0			
18	FFLTP; INFLUENT PIPE GALLEY	0			
19	MANHOLE 2PB	4			
20	MANHOLE 2IA-P	0			
21	MANHOLE 2IB-P	0			
22	NW CELL 2 (SEE MAP)	0			
23	SEE MAP	0			
24	SEE MAP	0			
25	MANHOLE 3A-S	0			
26	MANHOLE 3A-P	0			
27	FFMP005W	0			
28	FFMP013W[1]	NA	NA	NA	NA
29	FFMP016W[2]	NA	NA	NA	NA
30	TRUCKWASH DRAIN PIT	0			
31	MAINTENANCE BUILDING OFFICE	0			
32	MAINTENANCE BUILDING LUNCH ROOM	0			
33	MAINTENANCE BUILDING STORAGE AREA	0			
34	COMPLIANCE BUILDING LAB	0			
35	COMPLIANCE BUILDING OFFICE	0			
36	FFLTP EQ. TANKS METER PIT	0			
37	CELL 1 CLEANOUT	No Longer Monitored			
38	LASA PUMP STATION STRUCTURE INTERIOR	0			
39	LASA PUMP STATION AIR SPACE	0			
40	MANHOLE 4S	0			

[1] FFMP013W Location - Well Abandoned

[2] FFMP016W Location - Well Abandoned June 2021

FREY FARM LANDFILL METHANE MONITORING PROGRAM
SAMPLE POINT INSPECTION FORM

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 2/16/26	DATE	DATE	DATE
41	MANHOLE 4P	0			
42	MANHOLE 5S	0			
43	MANHOLE 5P	0			
44	MANHOLE 5SW[1]	NA	NA	NA	NA
45	MANHOLE 5PB[2]	NA	NA	NA	NA
46	MANHOLE 6S	0			
47	MANHOLE 6P	0			
48	MANHOLE 6-FM	0			
49	FFGMP001[3]	NA	NA	NA	NA
50	FFGMP002	0			
51	FFGMP003	0			
52	FFGMP004	0			
53	FFGMP005	0			
54	FFGMP006	0			
55	FFGMP007	0			
56	FFGMP008[4]	NA	NA	NA	NA
57	FFGMP01R	0			
58	FFGMP02R	0			
61	FFGMP08R	0			
	Atmospheric Pressure	29.96"			
	Air Temperature (Deg. C)	2.22°C			

[1] MANHOLE 5SW Location - removed due to FFVE
[2] MANHOLE 5PB Location - removed due to FFVE
[3] FFGMP001 Location - removed March 2018
[4] FFGM008 Location - removed April 2018